

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number INC0009349456	2. Page 1 of	3. Emergency Response Phone 765-289-2374	4. Manifest Tracking Number <b>010666298 JJK</b>			
5. Generator's Name and Mailing Address MID-CITY PLATING COMPANY, INC. 921 EAST CHARLES STREET MUNCIE, IN 47305				Generator's Site Address (if different than mailing address)				
Generator's Phone: 765-289-2374								
6. Transporter 1 Company Name <b>HERITAGE TRANSPORT, LLC</b>				U.S. EPA ID Number <b>IND058484114</b>				
7. Transporter 2 Company Name				U.S. EPA ID Number				
8. Designated Facility Name and Site Address HERITAGE ENVIRONMENTAL SERVICES 7901 W MORRIS STREET INDIANAPOLIS, IN 46231-3301				U.S. EPA ID Number INC093219012				
Facility's Phone: 704-773-9340								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type				
	x	1. RQ, UN3288, WASTE TOXIC SOLID, INORGANIC, N.O.S. (SODIUM CYANIDE), 6.1, POI, ERG-151 #44324-4	12	DM	660	G	F008	
		2.						
		3.						
		4.						
14. Special Handling Instructions and Additional Information NEEDS CD SENT TO US WASTE 24 HR EMERGENCY CONTACT MARC MUZZARELLI 765-289-2374 JS000039								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name <b>RODNEY MUZZARELLI</b>				Signature 		Month Day Year <b>7 28 15</b>		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:							
	Transporter signature (for exports only):							
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials							
	Transporter 1 Printed/Typed Name <b>LARRY TOWNSEND</b>				Signature 		Month Day Year <b>7 28 15</b>	
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name				Signature		Month Day Year	
	18. Discrepancy							
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
	Manifest Reference Number:							
	18b. Alternate Facility (or Generator)				U.S. EPA ID Number			
Facility's Phone:								
18c. Signature of Alternate Facility (or Generator)						Month Day Year		
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1.		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name				Signature		Month Day Year		